
Clarion Co., Ltd.
7-2, Shintoshin, Chuo-ku, Saitama-shi, Saitama 330-0081 Japan
Service Dept.: 7-2, Shintoshin, Chuo-ku, Saitama-shi 330-0081 Japan
Tel: +81-48-601-3705 FAX: +81-48-601-3804

Published by Service Dept.
298-6929-00 Jan.2011
Printed in Japan

Service Manual



Ford Motor Genuine
Satellite Digital Audio Radio
AM/FM/ Tuner CD Player

Model PU-3208L-P
(Genuine No. BT4T-19C107-BP)

Model PU-3208L-R
(Genuine No. BT4T-19C107-EA)

Model PU-3208L-S
(Genuine No. BT4T-19C107-EB)

Information on updated model

LF

This product is a lead free model.
Lead free solder is used in PWB stamped LF mark.
Please keep the following conditions when you repair.

1. Use lead free solder.
   * Koki's lead free solder S3X-55M 0.6mm
     (CLARION Parts No.642-0231-01)
   * Koki's lead free solder S3X-55M 1.0mm
     (CLARION Parts No.642-0231-02)
2. Use a nitrogen solder system.
3. Do not use "General solder" and "Lead free solder" together.

ORIGINAL MODEL

The original model of PU-3208L-P/R/S is PU-3208L-M/N.

Original model	Manual No.
PU-3208L-M/N	298-6787-00

< Update >

PU-3208L-M (BT4T-19C107-BM)
=> **PU-3208L-N** (BT4T-19C107-BN)
=> **PU-3208L-P** (BT4T-19C107-BP)
=> **PU-3208L-R** (BT4T-19C107-EA)
=> **PU-3208L-S** (BT4T-19C107-EB)

< Difference of software >

The software of E2PROM and the microcomputer was changed.

< Difference of hardware >

* SETPLATE
  PU-3208L-M: P/No. 276-0681-43
  PU-3208L-N: P/No. 276-0681-49
  PU-3208L-P: P/No. 276-0681-57
  PU-3208L-R: P/No. 276-0681-72
  PU-3208L-S: P/No. 276-0681-66

* TUNER PACK(Sirius) BL101
  PU-3208L-M: P/No. 941-0240-21
  PU-3208L-N: P/No. 941-0240-21
  PU-3208L-P: P/No. 941-0240-21
  PU-3208L-R: P/No. 941-0240-21
  PU-3208L-S: P/No. 941-0240-22