




SERVICE MANUAL

MONITOR WITH RECEIVER

**KW-M595BT, KW-M590BT, KW-M593BT,
KW-M595DBT, KW-M690BW, KW-M695BW,
KW-M695DBW**

SERVICE POLICY

No service parts available except accessory.




DC cable
E3A-1026-00
E3A-1027-00



Trim plate
B0H-0068-00




Extension parking cable
E3A-0344-00




Remover
D1C-0006-00




GPS antenna assy
T9A-0147-00



Sleeve
J3B-0034-00



Lever
J2B-0870-00



Microphone
T9B-0092-00



【Service Parts Configuration Table】

	KW-M595BT(K)	KW-M590BT(K)	KW-M590BT(M)	KW-M593BT(E)	KW-M595DBT(E)
E3A-1026-00	○	○			
E3A-1027-00			○		
E3A-1028-00				○	○
B0H-0068-00	○	○	○	○	○
E3A-0344-00	○	○	○	○	○
D1C-0006-00	○	○	○	○	○
T9A-0147-00	○	○	○	○	○
T9B-0092-00	○	○			
J3B-0034-00				○	○
J2B-0870-00				○	○

	KW-M690BW(K)	KW-M690BW(M)	KW-M695BW(K)	KW-M695DBW(E)
E3A-1026-00	○		○	
E3A-1027-00		○		
E3A-1028-00				○
B0H-0068-00	○	○	○	○
E3A-0344-00	○	○	○	○
D1C-0006-00	○	○	○	○
T9A-0147-00	○	○	○	○
T9B-0092-00	○		○	
J3B-0034-00				○
J2B-0870-00				○



JVC KENWOOD Corporation
Mobility & Telematics Services

【Revision History】

Date	Revision
2024/6/27	• Additional models KW-M593BT(E) KW-M595DBT(E)
2024/11/29	• Additional models KW-M690BW(K) KW-M690BW(M) KW-M695BW(K) KW-M695DBW(E)



JVCKENWOOD Corporation
Mobility & Telematics Services