


Service Manual



HDD Navigation System (40GB type)

Model **NAX980HD**
(QY-5001B-B)



This product is a lead free model.

Lead free solder is used in PWB stamped LF mark.

Please keep the following conditions when you repair.

1. Use lead free solder.
 - * Koki's lead free solder S3X-55M 0.6mm (CLARION Parts No.642-0231-01)
 - * Koki's lead free solder S3X-55M 1.0mm (CLARION Parts No.642-0231-02)
2. Use a nitrogen solder system.
3. Do not use "General solder" and "Lead free solder" together.

ORIGINAL SERVICE MANUAL

This additional service manual is designed to be used together with the original service manual.

Original model	Manual No.
NAX970HD (QY-5001B-A)	298-6399-00

* The hard disk was changed from 30GB to 40GB.

NAX970HD: 30GB HDD



NAX980HD: 40GB HDD

* Specifications and design are subject to change without notice for further improvement.

CAUTION

Use of controls, adjustment, or performance of procedures other than those specified herein, may result in hazardous radiation exposure.

The compact disc player should not be adjusted or repaired by anyone except properly qualified service personnel.



Bottom view of unit

EXPLODED VIEW / PARTS LIST

NO.	PART NO.	DESCRIPTION	Q'TY
1	372-3232-03	ALUMI FACE	1
15	276-0472-00	SETPLATE	1
16	-----	HARD DISC DRIVE(40GB)	1
17	331-3660-02	HDD BRKT	1

* Please refer to page 9 of the original service manual.

* Other parts are the same as NAX970HD.

* Software is different from NAX970HD.