
Clarion


Clarion Co., Ltd.
7-2,Shintoshin,Chuo-ku,Saitama-shi 330-0081 Japan
After Service Department: Phone +81-48-601-3792 / Fax +81-48-601-3804

Published by After Service Dept.
Printed in Japan
2012/12
No.E7424-00

Service Manual



UH-1104H-A (PH-3307H-C)



UH-1105H-A (PH-3309H-C)

HONDA Motor Genuine
FM/AM Radio Tuner
CD Player
(Hi-power LH type)

for USA

Model UH-1104H-A

(Genuine Parts Number 39100-SZT-A22)

Audio unit : PH-3307H-C

for CANADA

Model UH-1105H-A

(Genuine Parts Number 39100-SZT-C22)

Audio unit : PH-3309H-C

LF

This product is a lead free model.
Lead free solder is used in PWB stamped LF mark.
Please keep the following conditions when you repair.

1. Use lead free solder.
   * Koki's lead free solder S3X-55M 0.6mm
   (CLARION Parts No.642-0231-01)
   * Koki's lead free solder S3X-55M 1.0mm
   (CLARION Parts No.642-0231-02)
2. Use a nitrogen solder system.
3. Do not use "General solder" and "Lead free solder" together.

NOTES

* This product includes technology owned by Microsoft Corporation and cannot be used or distributed without a license from MSLGP.
* Specification and design are subject to change without notice for further improvement.
* ©Copyright 2012 Clarion Company,Ltd. All rights reserved.
No portion of this manual can be reproduced in any way, electronically or otherwise, without the express prior permission of the copyright owner.

ORIGINAL MODEL

The original model of PH-3307H-C is PH-3307H-A.
The original model of PH-3309H-C is PH-3309H-A.
Please refer to the service manual for PH-3307H-A, PH-3309H-A.

Original model	Manual No.
PH-3307H-A, PH-3309H-A	298-6774-00

< Difference of software >

The software of E2PROM and the microcomputer was changed.
(Audio data)

REFERENCE MODEL


The reference model of UH-1104H-A is UH-922U-01.
The reference model of UH-1105H-A is UH-924U-01.
Please refer to the service manual for UH-922U-01, UH-924U-01.

Original model	Manual No.
UH-922U-01, UH-924U-01	298-7156-00

COMPONENTS


UH-1104H-A, UH-1105H-A

1.	Main unit	----------	1
2.	Container assembly	----------	1/4
3.	Plastic bag	----------	1
4.	Inner carton	----------	1/4
5.	Label	----------	1/4



PH-3307H-C, PH-3309H-C

1.	Main unit	----------	1
2.	Carton	----------	1/4
3.	Packing	----------	1/4
4.	Packing	----------	1/4
5.	Plastic bag	----------	1
6.	Silicagel	----------	1
7.	Label	----------	1/4
8.	Plastic bag	----------	1
9.	CATS card	----------	1
10.	Setplate	----------	1
11.	Protector	----------	1
12.	Mounting bracket	300-8250-00	1



EXPLODED VIEW / PARTS LIST

Escutcheon section

The following parts are different from the original model.
Refer to the original service manual page 5.

NO.	PART NO.	DESCRIPTION	Q'TY
2	373-1216-20	DIAL-COVER (PH3307HC/PH3309HC)	1

Main section

The following parts are different from the original model.
Refer to the original service manual page 6.

NO.	PART NO.	DESCRIPTION	Q'TY
29	276-0866-38 276-0866-39	SETPLATE (PH3307HC) SETPLATE (PH3309HC)	1