

# JVC


## SERVICE MANUAL

### MONITOR WITH RECEIVER

**KW-M595BT, KW-M590BT, KW-M593BT,  
KW-M595DBT, KW-M690BW, KW-M695BW,  
KW-M695DBW**

#### SERVICE POLICY

No service parts available except accessory.




DC cable  
E3A-1026-00  
E3A-1027-00



Trim plate  
B0H-0068-00




Extension parking cable  
E3A-0344-00




Remover  
D1C-0006-00




GPS antenna assy  
T9A-0147-00



Sleeve  
J3B-0034-00



Lever  
J2B-0870-00



Microphone  
T9B-0092-00



**【Service Parts Configuration Table】**

	KW- M595BT(K)	KW- M590BT(K)	KW- M590BT(M)	KW- M593BT(E)	KW- M595DBT(E)
E3A-1026-00	○	○			
E3A-1027-00			○		
E3A-1028-00				○	○
B0H-0068-00	○	○	○	○	○
E3A-0344-00	○	○	○	○	○
D1C-0006-00	○	○	○	○	○
T9A-0147-00	○	○	○	○	○
T9B-0092-00	○	○			
J3B-0034-00				○	○
J2B-0870-00				○	○

	KW-M690BW(K)	KW-M690BW(M)	KW-M695BW(K)	KW-M695DBW(E)
E3A-1026-00	○		○	
E3A-1027-00		○		
E3A-1028-00				○
B0H-0068-00	○	○	○	○
E3A-0344-00	○	○	○	○
D1C-0006-00	○	○	○	○
T9A-0147-00	○	○	○	○
T9B-0092-00	○		○	
J3B-0034-00				○
J2B-0870-00				○



JVCKENWOOD Corporation  
Mobility & Telematics Services

**【Revision History】**

Date	Revision
2024/6/27	• Additional models KW-M593BT(E) KW-M595DBT(E)
2024/11/29	• Additional models KW-M690BW(K) KW-M690BW(M) KW-M695BW(K) KW-M695DBW(E)



JVCKENWOOD Corporation  
Mobility & Telematics Services